



1







2










3








4





5








1x

6










2x


7









8








9







10









1x

11





12








1x




1x


13









14








15









17

This diagram shows the assembly of a frame for the motor unit. A black Technic beam with a white connector is being attached to a blue and purple frame. Red lines indicate the alignment of the beam with the motor unit. The motor unit is shown with a yellow body and a grey top. A blue wheel is attached to the side of the motor unit. A black Technic beam is also shown being attached to the top of the motor unit. A black arrow points to the black Technic beam being attached to the frame.